


Punch Down Tool




STEP 1
Place UTP/STP cable on tool




STEP 2
Stripping Round Cable




STEP 3
Stripper UTP/STP Jacket



STEP 4



STEP 5
Punch down (RP-PD318)



Punch down and cut wire
(RP-PD224C)

